



Classification by
Robertson 1986



REFUSAL FROM ANCHORS FAILING



Location: WHAREROA	Position: X: 0.00 m, Y: 0.00 m	Ground level: 0.00	Test no: 3A
Project ID:	Client: CHEAL CONSULTANTS LTD	Date: 29/03/2010	Scale: 1 : 55
Project:	Page:	Page:	Fig: